

Listed Buildings by Parish

Kniveton

LB Ref	Address	Description	Grade	Date Listed
80112	Woodhead Farm Agnes Meadow Lane Kniveton Derbyshire DE6 1JR	Farmhouse. C17. Coursed rubble limestone with gritstone dressings. Mostly now roughcast. Plain tiled roof, stone coped gables with finials and central brick stack. Rear wing with stone slate roof with brick gable end stack. T-plan. Two-storeys with dormers. South elevation. Off-centre modern timber and rubblestone porch with half glazed door. Irregular fenestration including one, two, three and four light recessed chamfered mullion windows, some with dripstones. West elevation, whitewashed with a blocked four light recessed chamfered mullion window with dripstone on the groundfloor, a three-light chamfered mullion window with dripstone above, a similar window above again and a blocked single window with dripstone and a blocked single light with dripstone in the attic. North wing with one three light recessed chamfered mullion window. Listed for Group Value.	II	13/09/1967
80113	Gate Piers Woodhead Farm Agnes Meadow Lane Kniveton Derbyshire DE6 1JR	Gate piers. C18. Gritstone ashlar. Square on plan. Rusticated piers with moulded square caps and ball finials. Listed for Group Value.	II	13/09/1967
80114	Barn At Woodhead Farm Agnes Meadow Lane Kniveton Derbyshire DE6 1JR	Barn, C18. Coursed rubble limestone with gritstone dressings. Plain tiled roof with stone coped gables with kneelers and finials. Irregular openings with flat lintels and C19 brick segmental arches. At north end of west elevation one C18 window with chamfered surround. Listed for group value only.	II	20/10/1983

LB Ref	Address	Description	Grade	Date Listed
80115	Agnes Meadow Farm Agnes Meadow Lane Kniveton Derbyshire DE6 1JR	Farmhouse. C17 and C19. Coursed rubble limestone with gritstone dressings. Plain tiled roof with central brick stack. Two and three storeys. C19 brick lean-to extension at rear. South elevation with large gabled central porch with off-centre door. Irregular fenestration in varying degrees of mutilation. Two C17 windows remain intact, one two-light and one three-light with chamfered mullions. Some retain drip moulds. Flush quoins. East elevation with one three-light and one two-light chamfered mullion window with drip moulds both blocked. West elevation. Ground-floor with single light window and a two-light mullion window. Renewed two-light mullion window on first floor. Three-light recessed chamfered mullion window on second floor and two-light recessed chamfered mullion window in attic.	II	13/09/1967

LB Ref	Address	Description	Grade	Date Listed
80116	Horsley House Kniveton Derbyshire DE6 1JG	Farmhouse. Mid C17. Coursed rubble limestone with gritstone dressings. Tiled roofs, stone coped gables with finials and one brick gable end stack. Unequal T-plan. Two-storeys. West elevation from left to right. Doorway, now within a C20 part glazed porch, with chamfered surround and lintel inscribed 1640/WM SM. To the right of the later projecting wing another doorway with chamfered surround, lintel and dripmould. C19 half glazed door. To the right at ground level one 3-light and one 4-light low recessed chamfer mullion window lighting the cellar. One altered recessed chamfer mullion window above with dripmould and with one original mullion. First floor with one 4-light recessed chamfer mullion window. Later projecting wing with one flush 2-light chamfer mullion window on first floor with dripstone. Similar but altered window below. South, gable end, elevation. Ground floor with one 6-light recessed chamfer mullion window with dripmould. A similar 4-light window to first floor and a similar 3-light window in the gable. East elevation. Projecting off-centre stack with quoins. Irregular fenestration including two 3-light chamfer mullion windows, one with recessed mullions, which is now blocked, is in its present position a staircase window but is reset. Lower, C19 extension at the north end, part brick. In the loft one upper cruck truss with cross lapped face halved apex and collar. Interior with timber stud partitions with wattle and daub infil.	IISTAR	13/09/1967
80117	Mile Stone Between Horsley House Farm And Woodside Farm Fenny Bentley Derbyshire	Mile stone. C18. Flat stone inscribed TO/ASHBOURNE/3/MILES, TO/BAKEWELL/14/MILES.	II	20/10/1983

LB Ref	Address	Description	Grade	Date Listed
80118	Kniveton Methodist Church Chapel Lane Kniveton Derbyshire	Chapel. 1832. Stone plinth, red brick with tiled tipped roof. Square plan with projecting porch. Two round-arched windows to each facade with wooden glazing bars forming three stepped round-arched lights.	II	20/10/1983
80119	Sunday School Chapel Lane Kniveton Derbyshire DE6 1JP	Chapel. 1832. Brick with tiled roof. Rectangular plan. Central doorway with double plank doors. Flanked on each side by large windows with gothic metal glazing bars. Painted surrounds. Walls raised at angles of west facade to form parapet. Rendered pedimented gable.	II	20/10/1983
80120	Barn Brook Farm Foxholes Lane Kniveton Derbyshire DE6 1JN	Barn. Early C19. Coursed rubblestone with gritstone dressings and quoins. Plain tile roof. South elevation with two doorways With stone lintels and quoins and two former doorways, now blocked to form windows with similar lintels and quoins. Three other windows with glazing bar sashes. Loft doorway in the east gable end with lintel and quoins. Listed for group value only.	II	20/10/1983

LB Ref	Address	Description	Grade	Date Listed
80121	Brook Cottage Foxholes Lane Kniveton Derbyshire DE6 1JN	Formerly listed as Brook House. House. Late C17. Coursed rubble limestone with gritstone dressings. Tiled roof with brick gable end stacks. Two-storeys with single-storey wing to the south. Flush stone quoins. First floor string course. East elevation with doorway on the extreme left with moulded stone doorcase and pediment dated IB 1695. Modern half glazed door. Single light window above with chamfered surround. To the right a 2-light flush mullion window with square section mullion, on the ground floor and a 3-light chamfered mullion window above. To the right again a single light window with chamfered surround to each floor. To the right - again a 2-light flush mullion window with 3-light chamfered mullion window above; ie in the Sequence ABCB. Single-storey wing with one 2-light chamfered mullion window. North gable end with one 2-light and one 3-light chamfered mullion window with drip moulds. C20 wing to the west. Listed for Group Value.	II	13/09/1967
80122	Brook Farm Foxholes Lane Kniveton Derbyshire DE6 1JN	Farmhouse. C17 and C18. Coursed rubble limestone with gritstone dressings. Plain tile roof with brick gable end stacks and a central stack. East elevation with off-centre doorway with C20 half glazed door. Window to the right with small panes. To the left a window opening with C18 stone surround and chamfered sill. Later glazing bar casements. Similar window to the left and two similar windows above but without chamfered sills. West elevation with a blocked single light stair window with chamfered surround, a 3-light chamfered mullion window to the right and to the right again a single light window with chamfered surround. C20 lean-to to the left. According to F.Marston writing in the Derbyshire Archaeological Journal 1967, there is "one internal cruck frame with straight blades, arched tiebeam, collar and spurs (removed)". Interior not inspected. Listed for Group Value.	II	20/10/1983

LB Ref	Address	Description	Grade	Date Listed
80123	The Old Hall Foxholes Lane Kniveton Derbyshire DE6 1JN	House. C17 and C18. 'coursed rubble limestone with gritstone dressings. Tiled roof with brick gable end stack and stone coped gable with kneelers. L-plan with the angle filled in with mono pitched roof. Two-storeys. West front - double fronted. Stone quoins. Central doorway with stone doorcase with low pitched bracketed pediment. Six panelled door, raised and fielded. Rectangular light above. Flanked by glazing bar sashes with raised stone surrounds with keystones. Two similar windows above. South elevation with large projecting chimney stack. Two windows similar to those on the west front and to the left of the stack one blocked two light chamfered mullion window. One similar mullion window in the gable of the east facade. Listed for Group Value.	II	20/10/1983
80124	Pethills Lodge Foxholes Lane Kniveton Derbyshire DE6 1JP	Farmhouse. Early C19. Coursed rubble limestone with gritstone dressings. Tiled roof with stone coped gables and brick gable end stacks. T-plan with lower wing at the rear. Two and a half storeys. South elevation double fronted with flush stone quoins. Central doorway. Six panelled raised and fielded door. Rectangular overlight with gothick glazing bars. C20 flat hood. Flanked on either side by unusual windows with a fixed upper light with two pairs of diagonal glazing bars. Small paned casements beneath. Similar windows above and similar but smaller windows above again. The central windows are narrower.	II	20/10/1983

LB Ref	Address	Description	Grade	Date Listed
80125	St James Lane Farm Main Street Kniveton Derbyshire DE6 1JH	Farmhouse. Late C17. Coursed rubble limestone with gritstone dressings. Tiled roof with brick gable end stacks. Two-storeys. South elevation with off-centre doorway with rough stone lintel and quoins. Two light recessed chamfered mullion window above with lead paned windows. Three other similar windows one with C19 wooden casement. North elevation with one 2-light recessed chamfered mullion window and one single-light window with chamfered surround.	II	20/10/1983
80126	James Cottage Main Street Kniveton Derbyshire DE6 1JH	Cottage. Early C18 with later alterations. Coursed rubble limestone with gritstone dressings. Tiled roof with brick gable end stack. Two-storeys. Flush stone quoins. One 3-light chamfered stone mullion window to ground and to first floor. c1970s porch. Listed for Group Value.	II	20/10/1983
80127	Red Lion Main Street Kniveton Derbyshire DE6 1JH	Public House. Late C18. Coursed rubble limestone with gritstone dressings. Tiled roof with three brick gable end stacks. Two-storeys. Flush stone quoins. East elevation. Left hand half double fronted. Central porch built in 1981, flanked by glazing bar sashes with keystone lintels. Two similar glazing bar sashes above. The right hand half is of a different build with irregular fenestration. C20 casement windows. Listed for Group Value.	II	20/10/1983

LB Ref	Address	Description	Grade	Date Listed
80128	St Michaels Church Main Street Kniveton Derbyshire	Church. C12, 13, c1663, restoration 1870, vestry added 1907. Coursed rubble gritstone with ashlar dressings. Shallow pitched lead roof with stone coped gables at east and west end and over chancel arch. Nave and chancel, vestry, west tower and south porch. Plain C12 south doorway with chamfered imposts. Label with two stops, keystone depicting a bear. West tower, late C13 with small lancet window and plain chambered door to nave. String course at first floor. Square-headed 2-light bell openings, battlements and short spire are perp or later. North and south walls of church with irregular fenestration - all windows square headed, some without divisions others with chambered mullions. The lights in one north window have segmental heads. All probably mid C17. C19 chancel east window with perp style tracery. C13 font with circular bowl with pointed trefoils supported on a base of clustered columns. The date 1663 apparently refers to time of its restoration to the church. It might also be the date when the windows were renewed. West gallery early C19 on two cast iron columns. C19 poppy heads on benches. On nave north wall an aedicule wall monument to Greenwood Holmes 1779. Four C19 stained glass windows. Nave south, easternmost c1908 by Jones and Willis. Nave south, westernmost 1888. Nave north windows, three lights, 1908. Three light east window 1879.	I	13/09/1967

Total **17**